



Flashlights Improperly Marked with MSHA Emblem

Bayco Products Flashlight Model Numbers XXP-5420B, XXP-5420G, XPP-5422B, and XPP-5422G were improperly labeled with the MSHA emblem making it appear they were MSHA approved products. Bayco's website and advertising materials also improperly identified the flashlights as MSHA Approved. These flashlights are **NOT** MSHA approved and must not be used where MSHA approved equipment is required. Bayco flashlights with the MSHA emblem do not comply with Title 30 Code of Federal Regulations §75.1703 and 75.1703-1.

Bayco is new to the mining market. Bayco has not received MSHA Approval for any products at this time.

If you have an improperly labeled flashlight, return it to Bayco. Bayco has taken steps to stop distribution and sale of improperly labeled flashlights. Bayco has made application to MSHA for proper approval of the flashlights.



The flashlights are listed by Environmental Testing Laboratories (ETL) as intrinsically safe for use in hazardous locations. This listing is not affected.

The MSHA emblem is never used as stand alone approval marking, MSHA Approval, Certification, Acceptance, and Evaluation labels include a unique number to identify the specific product, manufacturer, and required